

Hydraulic pump adjustment on Racewell Trailer

Problem: Hydraulic Jack doesn't work lift/lower properly.



Photo 1 shows a large nut, remove this by turning anti clockwise.

TE PARI PRODUCTS

NEW ZEALAND:
PO BOX 25, 9 ENDEAVOUR CRESCENT, OAMARU 9400.
Ph: +64 3 433 0077 Em: sales.nz@tepari.com
FREEPHONE 0800 837 274

AUSTRALIA:
44 RICKY WAY, EPPING 3076 VICTORIA.
Fx: 1800 669 205 Em: sales.au@tepari.com
FREEPHONE 1800 650 682

USA:
14250 JUDICIAL ROAD, BURNSVILLE, MN 55306, USA.
Em: sales.usa@tepari.com
FREEPHONE 800 315 0433




Once nut is removed a large thread will be revealed with a flat screwdriver head on it.

TE PARI PRODUCTS

NEW ZEALAND:
PO BOX 25, 9 ENDEAVOUR CRESCENT, OAMARU 9400.
Ph: +64 3 433 0077 Em: sales.nz@tepari.com
FREEPHONE 0800 837 274

AUSTRALIA:
44 RICKY WAY, EPPING 3076 VICTORIA.
Fx: 1800 669 205 Em: sales.au@tepari.com
FREEPHONE 1800 650 682

USA:
14250 JUDICIAL ROAD, BURNSVILLE, MN 55306, USA.
Em: sales.usa@tepari.com
FREEPHONE 800 315 0433



Using a large blade screwdriver turn the thread clockwise to increase the pump output pressure. Screw in one full turn and then try the pump. Repeat until pump has enough pressure to lift trailer off the ground. Replace the large nut and tighten.

TE PARI PRODUCTS

NEW ZEALAND:
PO BOX 25, 9 ENDEAVOUR CRESCENT, OAMARU 9400.
Ph: +64 3 433 0077 Em: sales.nz@tepari.com
FREEPHONE 0800 837 274

AUSTRALIA:
44 RICKY WAY, EPPING 3076 VICTORIA.
Fx: 1800 669 205 Em: sales.au@tepari.com
FREEPHONE 1800 650 682

USA:
14250 JUDICIAL ROAD, BURNSVILLE, MN 55306, USA.
Em: sales.usa@tepari.com
FREEPHONE 800 315 0433